# Navajo Abandoned Uranium Mine

# Site Screen Report

This form is for use at the site of abandoned uranium mines (AUM) located on Navajo Nation lands. Applicable sites include all mine and mine features that have or have not undergone reclamation by the Navajo Abandoned Mine Lands Reclamation Program, including features, adits, pits and waste piles. Applicable sites also include all AUM sites listed in the USEPA CERCLIS database, all sites listed in the 2008 AUM GIS Report issued by USACOE and USEPA, all AUM sites on allotment lands associated with the Navajo Nation, and any and all AUM sites not listed in any database located on Navajo lands. Reconnaissance of any sites located on lands adjacent to Navajo lands that may be impacting Navajo lands will need to be coordinated with the authorities appropriate to those lands.

The purpose of the form is to ascertain the status and location of the identified AUM site, and record all immediate site information associated with the mine site. Decisions and recommendations on what additional steps are needed will be provided on a separate document.

## Tom Joe No. 6 AUM Site

Navajo AUM Northern Region

Prepared by:

Weston Solutions, Inc.

Contract: W91238-06-F-0083

12767.063.496.1111

March 2010

# Part I **Site Identification, Location and Status** Site Names and ID numbers as applicable **Mine ID:** 427 Map ID: N198 **CERCLIS:** NNN000908891 Navajo Abandoned Mine Land Reclamation Program: None **Local name / Aliases:** Tom Joe Claim No. 6; Tom Joe Claim No. 7 **Chapter and local area:** Round Rock Chapter County: Apache State: Arizona **Lat/Long:** 36.5409280453 N / -109.297757647 W **Nearby road and highway:** Indian Route 33 Local Post Office: Lukachukai, AZ Surface Land Status: check one or more and provide ownership and contact information below **Tribal Trust Land Public lands Private Tribal Fee Land Bureau of Land Mgmt Allotment** Fee land State **Subsurface Mineral Rights:** No information on subsurface mineral rights ownership was found in the EPA/AUM Database. **Claim and operator information:** The mine site surface land status is classified as Tribal Trust Land. Historical documents showed the operator of the mine as James W. Hall in 1963. No other historical ownership / lease information was identified in the EPA/AUM database. Number of residential structures within 200 feet of mine: None **Estimated volume of mine waste onsite:** $940 \text{ vd}^{3}$

#### Part II Summary of radiological readings

## Highest gamma radiation measurement:

237,267 counts per minute (cpm)

#### Describe any other radiological measurements:

A total of 1,131 gamma radiation measurements were collected from the mine site, ranging from 7,079 cpm to 237,267 cpm. Measurements in the vicinity of the waste debris offsite were found at levels above 200,000 cpm, measurements collected near the mine workings were consistent with background levels. The measurements are represented in Figures 1 and 2.


#### **Background Locations**

**Average background = 9,971** cpm

#1 8,359 cpm #2 11,852 cpm

#### **Distribution Chart and Statistics:**

The following chart and statistics were generated by ESRI ArcGIS 9.3.1, and show the general distribution of the site gamma radiation measurements. The horizontal X axis represents the gamma radiation reading levels in cpm (lowest levels to the left). The vertical Y axis represents the frequency of each gamma radiation level.



 Count:
 1131

 Minimum:
 7079,00000

 Maximum:
 237267,00000

 Sum:
 20254503,00000

 Mean:
 17908,49072

 Median:
 11850,00000

 Standard Deviation:
 32382,16126

#### Part III Status of Reclamation and Mine Waste

The following information was obtained from the Navajo Abandoned Mine Land Reclamation Program (NAMLRP) Point Features Database:

NAMLRP Status of the mine site: Reclaimed: No Waste Pile onsite: Yes

**NAMLRP Project Number:** None

**NAMLRP Mine features:** 1 Prospect

The following information was obtained from field observations collected during the 2009 site screening:

Provide description and status of all mine sites and features at site. Include all waste piles, adits, pits and other features, and indicate whether they are open, closed, covered, capped, buried or unreclaimed. Indicate approximate size, shape and extent, including description of any reclamation caps. Note condition of all caps.

Observed	reclam	ation	work	and	ctatue
Observed	тестани	41.IOH	WUIK	<b>711111</b> 1	SIALUS.

#### **Adits**

None

#### **Waste Piles**

Waste pile approximately 150' north of site, 10' x 8' with elevated readings; possible waste piles observed down cliff but inaccessible, with a total estimated volume of 940 yd<sup>3</sup>

#### Pits

None

#### **Shafts**

None

#### **Other Debris and Mine Features**

Numerous mine workings near site (car parts, pipes, wood debris)

#### **Part IV**

#### **Site observations and Environs**

Observed Structures: list number of and describe human habitation status of structures at the following distances from mine:

**0 to 200 feet:** None

200 feet to 0.25 mile: None

Observed Public or commercial structure: list and describe all schools, clinics, Chapter Houses, places of business and any other structure used by members of the community at the following distances:

0 to 200 feet: None

200 feet to 0.25 mile: None

Levels measured around the perimeter(s) of the identified structure(s):

None

Observed water sources: list the number and type of wells and surface water sources that are potentially used for human consumption at the following distances from the mine:

0 to 0.25 miles: None

**0.25 miles to 4 miles:** None

Sensitive environments: note and describe all sensitive environments located within visible range of the mine site, including: wetlands, endangered species, habitats and approximate locations of sites that may be under protection of the government of the Navajo Nation.

None observed

Known Site History: include information from interviews with Chapter officials and residents. Note information on mine ownership, type of mining operation, period of operation, known amount of production, and any other information as provided.

Tom Joe No. 6 mine consists of an area of 21,719.8 m<sup>2</sup>. The mine was identified as being operational in 1963. Historical documents showed the operator of the mine as James W. Hall in 1963. While operational, the mine had a total reported production volume of 29 tons. No other historical information or any additional ownership / lease information was identified in the EPA/AUM database.

## Part V Response Action Summary

**Site Name(s):** Tom Joe No. 6 **Chapter:** Round Rock

### **Decision Criteria**

Is there an unreclaimed waste pile at the site? Yes

At what distance from the waste pile is the nearest residential structure located? None

At what distances from the waste pile are there potential drinking water sources? None

Is there a reclamation cap or sealed adit in place at the site? Yes

Is the cap/seal functionally intact? Yes

Is the cap/seal sufficiently degraded to create a concern about releases? No

At what distance from the cap/seal is the nearest domestic structure located? None

At what distance from the cap/seal is the nearest domestic drinking water source? None

#### **Summary of emergency response factors**

None

## **Summary hazard ranking system factors**

None

#### **Summary of reclamation factors**

Unreclaimed waste piles

## Part VI Photos



Photo 1. Waste pile north of site



Photo 2. Evidence of mine workings



Photo 3. Evidence of mine workings



Photo 4. Abandoned bus on site



Photo 5. Cliff area



Photo 6. View down into lower portion of site


Name:

## Part VII Contacts Reports and Information

Stanley Edison (928) 871-6861

Eugene Esplain (928) 871-7331	
Title or official role (if any) Navajo EPA Superfund Program	
Address PO Box 2946, Window Rock, AZ 86515	
Information provided <u>Lead Regulatory Agency</u>	
Name	
Title or official role (if any)	
Address	
Telephone number	
Information provided	
Name	
Title or official role (if any)	_
Telephone number	_
Information provided	
Name	
Title or official role (if any)	
Telephone number	_
Information provided	_

Figure 1 - Gamma Radiation Measurements, Above Two Times Background
Tom Joe No. 6 (427)
Round Rock Chapter, Navajo Nation, Arizona



**Gamma Radiation Measurements** 

- < 2X Backgound</p>
- > 2X Background

Gamma survey conducted 10/2009 Measured as counts per minute (cpm)

Average background = 9,971 cpm








Figure 2 - Gamma Radiation Measurements Tom Joe No. 6 (427) Round Rock Chapter, Navajo Nation, Arizona



## Legend

#### **Gamma Radiation Measurements**

- 0 10,000
- 10,000 15,000
- 15,000 20,000
- 20,000 50,000
- 50,000 100,000
- > 100,000



Gamma survey conducted 10/2009 Measured as counts per minute (cpm)

Average background = 9,971 cpm

